



1982 Challenger 600

1982 Challenger 600

AIRFRAME

1982 Challenger 600

Total Time Since New:
Landings Since New:

9232 Hours
5423 Landings

ENGINES

Lycoming ALF-502L-2C

	Left	Right
Time Since New:	8669 Hours	7728 Hours
Cycles Since New:	5098 Cycles	4589 Cycles
MPI Interval:	2500 Hours	2500 Hours
Hours Available to Fly:	1104 Hours	1070 Hours

LC2 Performance Enhancement Engine Modifications

APU

GTCP-36-100 (E)

Time Since New:
APU Starts:

8376 Hours
5735

MAINTENANCE RECENTLY COMPLETED


- 6, 12, 24, 36, 48, 60 Month Inspections recently completed and delivered with a fresh Certificate of Airworthiness and Release to Service.
- Landing Gear Overhaul completed April 2023 and is next due April 2033.



1982 Challenger 600

AVIONICS

- Autopilot: Sperry SPZ-800 Autopilot
- EFIS: Honeywell EDZ-805 4-tube EFIS
- Flight Director: Dual Honeywell FZ-500
- Transponder: Dual Bendix King MST 67A MODE S
- TCAS II: Bendix King CAS TPU 67B w/ Ch. 7.1
- Radar Alt: Collins ALT-55
- Wx Radar: Honeywell Primus 800
- Comms: Dual Collins VHF-22D
- Stby Comms: Collins VHF-22B
- HF Comms: Dual Bendix King 951 with SELCAL
- Navs: Dual Collins VIR-32A
- ADF: Dual Collins ADF-60
- DME: Dual Collins DME-42
- LRN: Honeywell LASEREF INS
- CVR: Fairchild A100S Solid State CVR
- FDR: Fairchild F1000 Solid State FDR
- EGPWS: Honeywell Mark VII with Windshear
- FMS: Dual Global GNS-XLS with GPS



1982 Challenger 600

ADDITIONAL EQUIPMENT

- RVSM & BRNAV Compliant
- FM Immunity
- 8.33 Spacing
- RNP-10 & RNP-5 Capable
- L2C Engine Modifications
- Auto Ground Deploy Spoilers
- Winglets
- Airshow 400
- Fireblocked
- Thrust Reversers
- Two jumpseats
- Steer-by-Wire
- Fuel Tank Vent System
- Motorola VA-135 SELCAL
- Nose Gear Door Switch
- Pre-flight Fuel Quantity
- Dual Davtron 811B Clocks




1982 Challenger 600

INTERIOR – Refurbished 2014

Number of Passengers:	10
Configuration:	Four forward club seats, aft 4-place divan opposite 2 club seats.
Seating Finish:	Single Executive Seats completed in Vanilla leather. 4-Place Divan completed in a light brown fabric.
Woodwork:	Medium High Gloss Wood Veneer with brushed gold metal plating.
Carpet:	Calypso Dark brown carpet
Galley:	Forward located Galley consisting of several storage areas, a high temperature warming oven, coffee maker, cold storage area, display cabinet, sink and countertop.
Entertainment:	Dual Baker Audio Cabin Display, CD/DVD, Airshow 400, Individual Monitors to executive seating.
Lavatory:	Yes, fully enclosed aft private lavatory with vanity unit.
Baggage Area:	Yes, large aft baggage bay accessible in flight.


EXTERIOR – Painted 2013

Overall White with dark and light Silver Grey accent stripes.



1982 Challenger 600

Passenger Cabin – Floor plan



1982 Challenger 600



1982 Challenger 600




1982 Challenger 600



1982 Challenger 600



1982 Challenger 600



1982 Challenger 600



1982 Challenger 600



1982 Challenger 600





AVIATION EXCELLENCE


Interested?


Get in touch and we will assist you every step of the way in purchasing this aircraft.

PAUL WEINBERG

Director

 Paul@aviationx.co.za

 +27 (0) 82 850 0019

 +27 (0) 82 850 0019

If this aircraft is not the right one for you, let's have a conversation and we'll source the right aircraft for your needs

We deliver worldwide

Over 3,000 transactions completed



WWW.AVIATIONX.CO.ZA

Address

Hangar 108, Lanseria International Airport
South Africa, 1739



AVIATION EXCELLENCE

Why Choose Aviation X?

Aviation X is located at Lanseria International Airport, Johannesburg, South Africa. Our team of seasoned aircraft sales professionals collectively have almost a century of aviation experience and have completed over 3,000 successful aircraft purchase and sale transactions. We offer aircraft financing solutions through our finance partner and maintain excellent relationships with South Africa's leading lending institutions.

Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties. Verification of specifications remain the sole responsibility of purchaser. Photographs and images may have been modified to remove logos, registration marks, or other identifying information to protect the privacy of the Aircraft's current owner. The Aircraft is subject to prior sale, lease, and/or removal from the market without prior notice.

We deliver worldwide
Over 3,000 transactions completed



WWW.AVIATIONX.CO.ZA

Address
Hangar 108, Lanseria International Airport
South Africa, 1739